

IMPORTANT NOTE

THE MCE SOLUTION IS SELF-CONTAINED. SOFTWARE UPDATE AND EXISTING BOARD MODIFICATION TO THE CONTROLLER IS NOT NECESSARY FOR THIS PRODUCT. CONTRACTORS ARE RESPONSIBLE FOR FIELD AND HOIST WAY WIRING AND INSTALLATION OF DPM SWITCHES.

Please be advised that the unauthorized use of third-party, Door Lock Monitoring ("DLM") products for purposes of Georgia "GA" code compliance on any Motion Control Engineering ("MCE") controls will immediately and indefinitely void all support from MCE for the altered



Page 2 / 5

HQ: 11380 White Rock Road Rancho Cordova, CA 95742  
EIN 27-3330722

Bill-to address

Summit Elevator

Number/Date

20388870 / April 23, 2024

**controller.** While MCE is generally aware there are third party providers on the market, MCE has not reviewed, tested, or approved the effects of any of those alterations on our equipment. Without any review and testing, we cannot guarantee the electrical soundness of the changes, including, any negative side effects they might have with the control software, the integrity of all safety and door lock circuits, and the satisfaction of all the requirements for code compliance. MCE shall not be liable for, and hereby disclaims, any liability arising from or relating to third party DLM product installed on our equipment. Such disclaimer shall include damages done to the third-party components, the controller, peripheral components, and building properties. Further, MCE shall be held harmless from and against any personal injuries, or, loss of life where an unauthorized third-party solution is used on MCE equipment. Please contact MCE Technical Support at [techsupport@nidec-mce.com](mailto:techsupport@nidec-mce.com) if you have any further questions or require further clarification of this policy.